


# CAUTION!

## SPECIAL ASSEMBLY INSTRUCTIONS

*Failure to follow the instructions will void the warranty on this pump.*

When installing the pump on 1977 and earlier vehicles, a 3/16" thick spacer is required. This spacer is installed between the pump and the alternator or A/C mounting bracket.

(See illustration)



Although care has been taken to assure the accuracy of the data compiled in this publication, the manufacturer does not assume any liability for errors or omissions.